PRINTED

05/28/2025
------------

06/04/2025

### JACKSON COUNTY SCHOOL BOARD

ATTN:ACCOUNTS PAYABLE PO BOX 5958 MARIANNA, FL 32447

PAGE	1	OF	1
------	---	----	---

#### REQUISITION NUMBER

01	ハウビ	nn	NE A
01	025	υυ	U34

VENDOR KEY	: COFFMAN 000
SHIP DATE	: 05/28/2025
FISCAL YEAR	: 2024-2025
ENTERED BY	: MELVIJEA000

VENDOR: COFFMAN INTERNATIONAL INC 4185 ROSS CLARK CR NE DOTHAN, AL 36303 SHIP TO: JACKSON COUNTY SCHOOLS MAINTENANCE D 3528 RUSSELL ROAD MARIANNA, FL 32446

PHONE: (334) 794-4111 FAX: (344) 792-0424

ATTN: JEAN MELVIN

QUANTITY	UNIT	DESCRIPTION OF ITEMS OR MATERIALS		UNIT PRICE	AMOUNT
1	EACH	Repairs needed for International Dump Truck.	Repair	10759.95000	10,759.95
		transmission, replace clutch, resurface flywh	eel, replace rear		
		main seal, repair power steering leak, repair			
		working), replace leaking rocker box gaskets,	oil and filter		
		change and replace leaking A/C hose.			
		ACCOUNT SUMMARY (FOR INTERNAL U	SE)		
		ACCOUNT NUMBER	ACCOUNT AMOUNT		
		1000E8100 3500 9001 81000 00000 00000	10,759.95		
		NOTES			
		PENDING BOARD APPROVAL ON 06/17/2025 - EF			
	-	•		PAGE TOTAL	10,759.95
				TOTAL	10,759.95

This is a Requisition and not an official Purchase Order. The District is not financially responsible for the unauthorized purchases made with a Requisition.



## COFFMAN INTL INC. 4185 ROSS CLARK CIR. - DOTHAN, AL 363034480 Phone: (334) 794-4111 - Fax: (334) 792-0424 (Service Writer: David Worthy - Date: 5/21/2025 8:26 AM C)

Estimate #4848332 Prepared For

Jackson County School Board 2789 Pennsylvania Ave., Marianna, FL 324484025 (primary) Phone: (1) 850-4829613 - Fax: () -(VIN: 1HTTYAHT17J427768 - Unit: 07290)

# Repair Management

### COFFMAN INTL INC.

4185 ROSS CLARK CIR. - DOTHAN, AL 363034480 Phone: (334) 794-4111 - Fax: (334) 792-0424 Estimate Number: 4848332 - RO Number: 22344 Service Writer: David Worthy - Date: 5/21/2025 8:26 AM (C)



Currency: USD

## Unit No: 07290

### **Jackson County School Board**

VIN: 1HTTYAHT17J427768	Recall/AFC: No
Model: 7700 SBA 6X4 Engine: CUM ISM-425V 410HP @2100 RPM Make: International Delivered: 11/10/2008 In Service: 16 Years 6 Months Mileage: 110684 Eng Hrs: 3859	Contact Name: Randy Ward Position: primary Phone: (850) 482-9613 E-Mail: PO Number:

Operation (All Sections)	Labor Cost	Parts Cost	Core Charge	Total Cost
REBUILD: BENCH TIME - 9/10 SPEED (TOP LOAD)	\$3,700.00	\$699.72	\$0.00	\$4,399.72
<ul> <li>(4) RING RETAINING</li> <li>(1) GASKET SHIFT BAR HSG</li> <li>(1) RING SNAP</li> <li>(1) RING SNAP INPUT SHAFT</li> <li>(2) CLUTCH TRANS MASHFT SLIDING</li> <li>(1) CLUTCH TRANS MASHFT SLIDING</li> <li>(1) FILTER,KIT AIR FILTER &amp; REGULA</li> <li>(2) RING SNAP</li> <li>(1) RING O FOR GROOVED PLUG</li> <li>(1) PISTON RANGE CYLINDER</li> <li>(1) RING O</li> <li>(1) O-RING, TRANSMISSION</li> <li>(1) NUT CTSHFT REAR BRG OR FRT</li> <li>(1) O-RING, TRANSMISSION</li> <li>(1) KT ORING,KIT O RINGS &amp; GASKETS</li> <li>(1) KT CYLDR,KIT AIR CYL REPAIR</li> <li>(1) NUT, 1/2-20 ELS STOP</li> <li>(1) COVER SHIFT CYLINDER</li> <li>(1) GASKET CLUTCH HOUSING</li> <li>(1) GASKET FRONT BRG COVER</li> <li>(1) COVER,GASKET CASE REAR HSG</li> <li>(1) DIRECT SHIP FREIGHT</li> <li>(28) 50W SYNTHETIC</li> </ul>				
HEAVY CLUTCH (1) BEARING BALL	\$277.50	\$1,211.10	\$0.00	\$1,488.60
(1) CLUTCH ASSY (1) HARDWARE,CLUTCH INSTALLATION K				
RESURFACE FLYWHEEL	\$0.00	\$101.25	\$0.00	\$101.25
REAR MAIN SEAL	\$277.50	\$194.65	\$0.00	\$472.15
(1) KIT, SEAL (1) DIRECT SHIP FREIGHT				
REPAIR POWER STEERING LEAK	\$185.00	\$82.37	\$0.00	\$267.37
(1) GASKET RESERVOIR CAP/CANISTER (1) FILTER, OIL, P/S RESERVOIR (2) FLEETRITE POWER STEERING 32OZ (1) FLTRTE CHLORINATED BRAKE CLEAN				
REPAIR AIR HORN NOT WORKING	\$92.50	\$58.66	\$0.00	\$151.16
(1) KT XMSN,KIT AIR HORN SOLENOID				

	11		1	
REPLACE LEAKING ROCKER BOX GASKETS	\$1,720.50	\$492.83	\$0.00	\$2,213.33
(1) ROCKER LEVER HOUSING GASKET (4) SEAL,O RING (1) SEAL,GROMMET (16) SPACER,MOUNTING (1) GASKET,ROCKER LEVER COVER (1) INBOUND FREIGHT				
OIL AND OIL FILTER CHANGE	\$92.50	\$211.32	\$0.00	\$303.82
(1) OIL FILTER, NANONET USED ON CUMMINS ISX15 ENGINES (38) ENGINE OIL (1) WASTE OIL				
REPLACE LEAKING A/C HOSE	\$647.50	\$493.05	\$0.00	\$1,140.55
(1) HOSE ASSY ACCUMULATOR TO COMPR (1) CRITICAL ORDER FREIGHT (2) SEALING WASHER AND O-RING KIT; TYPE: SEALING WASHER AND O-RING KIT (3) R134A REFRIGERANT (PER #)				
STEAM CLEAN	\$74.00	\$0.00	\$0.00	\$74.00
ROAD TEST	\$55.50	\$0.00	\$0.00	\$55.50
Notes: [5/21/2025 8:26 AM] - Dealer: ESTIMATE TO MAKE NEED NO CD BUT WENT ON RT WITH ADAM & AT FIRST TRA SHIFTING OUT FINE BUT THEN WE DUPLICATED THE DEFINANTLY JUMPING OUT OF 3RD & 7TH & SEEMED THE TEMP GOT THE WORSE THE TRANSMISSION GOT KNOW IF AC WAS A PREVIOS ISSUE BUT ON THE WAY SMOKE & SMEELED SOMETHING, AC STOPPED COOL	NSMISSION WAS COMPLAINT, IT"S THE HOTTER f & I DON"T f BACK WE SAW ING & WHEN WE	Labor: Shop: Tax:	<b>`</b>	\$3,544.95 \$0.00 \$7,122.50 \$92.50 \$0.00
GOT BACK & OPENED THE HOOD WE SAW AC COMPR THE TRANSMISSION ISSUE IT HAS TO BE REMOVED & NEED TO REPLACE SLIDING CLUTCHES, 3RD & 4TH G STEERING RESERVIOR LEAKING, WILL NEED TO REPL CONNECTED WITH PC AND SWITCH IS WORKING BUT FOR FAN IS NOT. WILL NEED TO REPLACE AIR SOLEN HORN CUMMINS ISM - ROCKER BOX LEAKING	BARE MINIMUM EAR CAP ON ACE SEALS AIR SOLENOID	TOTAL:		\$10,759.95

## Estimate #4848332

## Labor Card

Customer: Jackson County School Board Vehicle: 7700 SBA 6X4 VIN: 1HTTYAHT17J427768 Unit: 07290

RO: 22344 Mileage: 110684 Date: 5/21/2025

#### Time: 20.0 REBUILD: BENCH TIME - 9/10 SPEED (TOP LOAD)

Variation:	REPAIR TRANSMISSION JUMPING OUT OF 3RD AND 7TH GEAR
Standard Operation Notes:	N/A
Additional Notes:	N/A

#### Time: 1.5 HEAVY CLUTCH

Variation:	REPLACE CLUTCH WHILE REPAIRING TRANSMISSION ISSUE	
Standard Operation Notes:	N/A	
Additional Notes:	N/A	

#### Time: 0.0 RESURFACE FLYWHEEL

Variation:	RESURFACE FLYWHEEL
Standard Operation Notes:	N/A
Additional Notes:	N/A

#### Time: 1.5 REAR MAIN SEAL

Variation:	REPLACE REAR MAIN ENGINE OIL SEAL IF NEEDED WHILE REPAIRING TRANSMISSION
Standard Operation Notes:	N/A
Additional Notes:	N/A

#### Time: 1.0 REPAIR POWER STEERING LEAK

Variation:	A2- REPAIR POWER STEERING LEAK
Standard Operation Notes:	N/A
Additional Notes:	N/A

#### Time: 0.5 REPAIR AIR HORN NOT WORKING

Variation:	A2- REPAIR AIR HORN NOT WORKING
Standard Operation Notes:	N/A
Additional Notes:	N/A

#### Time: 9.3 REPLACE LEAKING ROCKER BOX GASKETS

Variation:	A2- REPLACE LEAKING ROCKER BOX GASKETS
Standard Operation Notes:	N/A
Additional Notes:	N/A

#### Time: 0.5 OIL AND OIL FILTER CHANGE

Variation:	CHANGE ENGINE OIL AND OIL FILTER
Standard Operation Notes:	N/A
Additional Notes:	N/A

#### Time: 3.5 REPLACE LEAKING A/C HOSE

Variation:	A2- REPLACE LEAKING A/C HOSE
Standard Operation Notes:	N/A
Additional Notes:	N/A

#### Time: 0.4 STEAM CLEAN

Variation: STEAM CLEAN Standard Operation Notes: N/A Additional Notes: N/A

#### Time: 0.3 ROAD TEST

Variation: ROAD TEST Standard Operation Notes: N/A Additional Notes: N/A

## Estimate #4848332

Customer: Jackson County School Board Vehicle: 7700 SBA 6X4 Mileage: 110684 VIN: 1HTTYAHT17J427768 RO: 22344 Date: 5/21/2025

#### **REBUILD: BENCH TIME - 9/10 SPEED (TOP LOAD)**

Qty	Part Number	Part Name	Price (ea)	Total
4	FUL4303336	RING RETAINING	\$2.86	\$11.44
1	FUL4302676	GASKET SHIFT BAR HSG	\$4.40	\$4.40
1	FUL16763	RING SNAP	\$0.97	\$0.97
1	FUL14750	RING SNAP INPUT SHAFT	\$0.94	\$0.94
2	FUL4306648	CLUTCH TRANS MASHFT SLIDING	\$40.14	\$80.28
1	FUL4306647	CLUTCH TRANS MASHFT SLIDING	\$37.50	\$37.50
1	FULK2170	FILTER, KIT AIR FILTER & REGULA	\$65.88	\$65.88
2	FUL14317	RING SNAP	\$0.79	\$1.58
1	FUL14765	RING O FOR GROOVED PLUG	\$1.63	\$1.63
1	FUL14341	PISTON RANGE CYLINDER	\$25,50	\$25.50
1	FUL14345	RING O	\$0.81	\$0.81
1	FUL14344	O-RING, TRANSMISSION	\$11.94	\$11.94
1	FULX11010	NUT CTSHFT REAR BRG OR FRT	\$1.06	\$1.06
1	FUL14644	O-RING, TRANSMISSION	\$4.73	\$4.73
1	FULK2054	KT ORING, KIT O RINGS & GASKETS	\$20.62	\$20,62
1	FULK2427	KT CYLDR,KIT AIR CYL REPAIR	\$20.94	\$20.94
1	FULX1803	NUT, 1/2-20 ELS STOP	\$1.31	\$1.31
1	FUL21329	COVER SHIFT CYLINDER	\$150.98	\$150.98
1	FUL4308226	GASKET CLUTCH HOUSING	\$22.03	\$22.03
1	FUL14311	GASKET FRONT BRG COVER	\$0.98	\$0.98
1	FUL14335	COVER, GASKET CASE REAR HSG	\$3.24	\$3.24
1	INBOUND FREIGHT	DIRECT SHIP FREIGHT	\$75.00	\$75.00
28	SYNTHETIC LUBE	50W SYNTHETIC	\$5.57	\$155,96

#### HEAVY CLUTCH

Qty	Part Number	Part Name		Price (ea)	Total
1	2004507C1	BEARING BALL		\$33.64	\$33.64
1	C30970182	CLUTCH ASSY		\$973.10	\$973.10
1	CK2468CL	HARDWARE, CLUTCH INSTA	LLATION K	\$204.36	\$204.36

#### **RESURFACE FLYWHEEL**

Qty	Part Number		Price (ea)	Total
		No parts assigned		

#### **REAR MAIN SEAL**

Qty	Part Number	Part Name	Price (ea)	Total
1	4089542	KIT, SEAL	\$144.65	\$144.65
1	INBOUND FREIGHT	DIRECT SHIP FREIGHT	\$50.00	\$50.00

#### **REPAIR POWER STEERING LEAK**

## Parts Card

Qty	Part Number	Part Name	Price (ea)	Total
1	2507061C1	GASKET RESERVOIR CAP/CANISTER	\$15.80	\$15.80
1	4043517C1	FILTER, OIL, P/S RESERVOIR	\$44.46	\$44.46
2	FLTPSF32KK	FLEETRITE POWER STEERING 320Z	\$8.51	\$17.02
1	FLTACBC185KK	FLTRTE CHLORINATED BRAKE CLEAN	\$5.09	\$5.09

#### **REPAIR AIR HORN NOT WORKING**

Qty	Part Number	Part Name	Price (ea)	Total
1	2506713C91	KT XMSN,KIT AIR HORN SOLENOID	\$58.66	\$58.66

#### **REPLACE LEAKING ROCKER BOX GASKETS**

Qty	Part Number	Part Name	Price (ea)	Total
1	4070529	ROCKER LEVER HOUSING GASKET	\$100.72	\$100.72
4	3049221	SEAL,O RING	\$3.08	\$12.32
1	3042401	SEAL,GROMMET	\$3.35	· \$3,35
16	3883222	SPACER, MOUNTING	\$12.14	\$194.24
1	3883220	GASKET,ROCKER LEVER COVER	\$132.20	\$132.20
1	INBOUND FREIGHT	INBOUND FREIGHT	\$50.00	\$50.00

#### OIL AND OIL FILTER CHANGE

Qty	Part Number	Part Name	Price (ea)	Total
1	LF14000NN	OIL FILTER, NANONET USED ON CUMMINS ISX15 ENGINES	\$33.91	\$33.91
38	15W40	ENGINE OIL	\$4.57	\$173.66
1	wo	WASTE OIL	\$3.75	\$3.75

### **REPLACE LEAKING A/C HOSE**

Qty	Part Number		Price (ea)	Total
1	3576339C91	HOSE ASSY ACCUMULATOR TO COMPR	\$267.84	\$267.84
1	INBOUND FREIGHT	CRITICAL ORDER FREIGHT	\$175.00	\$175.00
2	FLTACMT1319	SEALING WASHER AND O-RING KIT; TYPE: SEALING WASHER AND O-RING KIT	\$3.94	\$7.88
3	ZGGR6330LB	R134A REFRIGERANT (PER #)	\$14.11	\$42.33

#### **STEAM CLEAN**

, <u> </u>				
STEAM CLEAN		na La sera de la sera de l		n de la companya de l La companya de la comp
Qty Part Number	Part Name		e (ea)	Total
	No parts assigned	-beers and the first second of the second		1997) 1997)

#### **ROAD TEST**

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		